

4/6/2016

GAS TRANSMISSION WORK ORDER

SEU

WORKORDER

WORK ORDER #: **6102594**

PMNUM:

PARENT WO #:

DESCRIPTION: VALVE TESTING FF-38A (SEE COMMENTS BELOW)

037-24230

TARGET START DATE:

ROUTE NUMBER:

TARGET COMP DATE: 5/5/2016

STATUS: INPRG

SCHEDULE START:

REQUESTED BY: DMAINE

SCHEDULE FINISH:

REPORT DATE: 4/6/2016

PM ACTIVITY CLASS:

ASSET #: 24845

ASSET DESCRIPTION: GROUP 1 WELLS

LOCATION ID: AC-GROUP 1 WELLS

LOC. DESCRIPTION: FF-32,33,34,35,38, MA-1A,1B,3,4, P-14,68A,68B

PHYSICAL LOCATION:

RESPONSIBLE SUPERVISOR / OWNERWORK TYPEPRIORITYACCOUNT INFO

FIELD MAINT /

CM

2

26357.003

REMARKS: UNABLE TO PERFORM TEST, WELL
IS LOCKED OUT AND BLOWN DOWN.

4-6-16

Date Completed

~~FF-38A IS ON WELL.~~

DMAINE

Completed By

SAFETY CHECKLIST COMPLETED?

Estimated Labor HoursLabor Code/CraftQuantityPlanned HoursActual Hours

0

.25

COMMENTS:

PERFORM FUNCTION AND ISOLATION TEST ON THE MASTER VALVE, TUBING PRODUCTION WING VALVE AND THE CASING PRODUCTION WING VALVE

LOCATION METERS:

LOG: